

Nazi documentation Vogelsang

Vogelsang 70
53937 Schleiden

Tel: +49 2444 91579-17

info@vogelsang-ip.de
<http://www.vogelsang-ip.de>

Information for people with hearing impairments and deaf people

Information on accessibility was evaluated and verified on July 6, 2021 as part of the quality criteria / system "Tourism for all".

Images of the building/object



Exhibition

© Vogelsang IP Roman Hövel



Exhibition

© Vogelsang IP Roman Hövel



Nazi documentation
Vogelsang

©Guido Frank



Nazi documentation
Vogelsang

©Guido Frank

Parken



Parken

©Guido Frank

Parking lot



Parking lot

©Guido Frank



Parking lot

©Guido Frank

There is no company parking available.

There is/are 4 parking space(s) for people with disabilities.

Parking space width: 350 cm

Parking space length: 500 cm

Distance from the parking space(s) for people with disabilities to the entrance area: 170 m

The parking space(s) for people with disabilities is/are not marked.

ÖPNV-Haltestelle



ÖPNV-Haltestelle

©Guido Frank

Train/Bus platform/Ship dock



Entrance



Entrance

©Guido Frank



Entrance

©Guido Frank

Elevator/lift



Elevator/lift

©Guido Frank



Elevator/lift

©Guido Frank



Elevator/lift

©Guido Frank

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system. An outgoing emergency call in the elevator is confirmed visually, e.g. by a digitally printed text field.

Checkout / Cash desk



Checkout / Cash desk

©Guido Frank

Counter/Cash Desk



The cash register display/price indication at the register is not easily recognizable (e.g. large and swiveling).

Elevator/lift



Elevator/lift

©Guido Frank



Elevator/lift

©Guido Frank



Elevator/lift

©Guido Frank

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system. An outgoing emergency call in the elevator is confirmed visually, e.g. by a digitally printed text field.

Showrooms



Showrooms

©Guido Frank

Entrance area



Entrance area

©Guido Frank

Additional information only available in German: Schranke mit Durchgangsbreite 120 cm.

Showroom/Hall

Showroom/Hall



Showroom/Hall

©Guido Frank



Showroom/Hall

©Guido Frank



Showroom/Hall

©Guido Frank



Showroom/Hall

©Guido Frank

Information is provided in writing. There is audible information. Information can be captured tactilely (braille, prismatic font). Information is displayed photo realistically.

Showroom/Hall





Showroom/Hall

©Guido Frank



Showroom/Hall

©Guido Frank



Showroom/Hall

©Guido Frank

Information is provided in writing. There is audible information. Information can be captured tactilely (braille, prismatic font). Information is displayed photo realistically.

Other technical possibilities of information: Mediaguide


Elevator/lift

Elevator/lift



Elevator/lift

©Guido Frank



Elevator/lift

©Guido Frank

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system.

Elevator/lift



Elevator/lift

©Guido Frank

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system.

Public toilet



Public toilet

©Guido Frank

Public toilet

Public toilet





Additional information only available in German: Ein Wickeltisch für Kinder ist vorhanden.

Public toilet



Public toilet

©Guido Frank

Additional information only available in German: Ein Wickeltisch für Kinder ist vorhanden.

Shop

Elevator/lift



Elevator/lift

©Guido Frank



Elevator/lift

©Guido Frank



Elevator/lift

©Guido Frank

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system. An outgoing emergency call in the elevator is confirmed visually, e.g. by a digitally printed text field.

Aids

Alarm/Aids



There is no alarm.

Elevator/lift: Aufzug im Foyer

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system. An outgoing emergency call in the elevator is confirmed visually, e.g. by a digitally printed text field.

Elevator/lift: Aufzug in der Ausstellung 1

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system.

Elevator/lift: Aufzug in der Ausstellung 2

An outgoing emergency call in the elevator is confirmed audibly, e.g. by an intercom system.

There is no audio induction loop at the counter/reception desk.

Wheelchair, Audio guides

Audioguide is available. Multimedia Guide is available. Movies are available.

Führungen

Guided tours